



1/4" 4-IN-1 BALL VALVE TOOL



 [VIEW LARGER](#)

OVERVIEW

4-in-1 ball valve tool is perfect for vacuum, charge, cores and recovery. Remove and replace Schrader cores without losing charge.

 [Download Image](#)

 [Email Info](#)

FEATURES —

UPCs +

This versatile tool for the lo- or hi- side of a system does four jobs:

1. **Vacuum valve.** Extra 1/4" side port on the 18975 to attach electronic micron vacuum right at the system for greater accuracy or to add refrigerants. Working pressure of 800 psi.
2. **Core removal access.** Lets you evacuate and charge through an unrestricted line for increased speed and higher vacuum.
3. **Core replacement.**
4. **Recovery valve.** Core removal allows recovery unit to work at maximum efficiency, speeding the recovery process.

Made in the USA

HOME

PRODUCTS +

ABOUT

RESOURCES +

SUPPORT +

NEWS & EVENTS

CONTACT US

REP LOGIN

SUBSCRIBE TO "THE BUZZ" NEWSLETTER

Enter your email here *



YELLOW JACKET UNIVERSITY

Get your degree in cool >