



Viega PEX Press adapter
Smart Connect feature, Zero Lead
 - For transitioning between Viega PEX Press and Viega ProPress
 - Bronze
 - Press connection
components
 EPDM sealing elements
Note
 ProPress tool and jaw required
Model 2813PZL

P1	P2	Wt [lb]	Quantity	Part No	DG
1/2	1/2	0.075	10	99620	6
1/2	3/4	0.114	10	99626	6
3/4	1/2	0.077	10	99630	6
3/4	3/4	0.113	10	99640	6
1	3/4	0.136	10	99645	6
1	1	0.185	10	99660	6
1 1/4	1	0.231	5	99665	6
1 1/4	1 1/4	0.284	5	99670	6
1 1/2	1	0.276	5	99675	6
1 1/2	1 1/2	0.444	5	99680	6
2	1	0.459	5	99685	6
2	2	0.719	5	99690	6



Viega PEX Press adapter
Zero Lead
 - Bronze
 - Press connection, female copper tube size
Model 2813.5ZL

P	C	Wt [lb]	Quantity	Part No	DG
3/8	1/2	0.061	10	92006	6
1/2	1/2	0.063	10	92021	6
1/2	3/4	0.098	10	92026	6
3/4	1/2	0.066	10	92036	6
3/4	3/4	0.116	10	92041	6
3/4	1	0.172	10	92045	6
1	1	0.187	10	92060	6
1 1/4	1 1/4	0.331	5	92070	6
1 1/2	1 1/2	0.450	5	92080	6
2	2	0.609	5	92090	6



Viega PEX Press adapter
Zero Lead
 - Bronze
 - Press connection, street
Note
 ProPress tool and jaw required
Model 2813.1ZL

P	FTG	Wt [lb]	Quantity	Part No	DG
1/2	1/2	0.064	10	97520	6
1/2	3/4	0.097	10	97525	6
3/4	1/2	0.079	10	97535	6
3/4	3/4	0.100	10	97540	6
3/4	1	0.154	10	97545	6
1	1	0.174	10	97560	6
1 1/4	1 1/4	0.304	5	97570	6
1 1/2	1 1/2	0.434	5	97580	6
2	2	0.696	5	97590 ¹	6

¹ For use with solder fittings only.



Viega PEX Press adapter
Zero Lead
 - Bronze
 - Press connection
Note
 2" ProPress tool and jaw required
Model 2813.3ZL

P	FTG	Wt [lb]	Quantity	Part No	DG
2	2	0.736	5	97690 ¹	6

¹ For use with ProPress fittings only.



Viega PEX Press adapter
Zero Lead
 - Bronze
 - Press connection, polybutylene (PB) connection
Note
 Does not include ring for PB connection
Model 2813.2ZL

P	PB	Wt [lb]	Quantity	Part No	DG
1/2	1/2	0.051	10	97820	6
3/4	3/4	0.073	10	97840	6



Viega PEX Press adapter
Zero Lead
 - Bronze
 - Press connection, flare connection
Model 2892ZL

P	Flare	Wt [lb]	Quantity	Part No	DG
3/4	3/4	0.275	10	97140	6
1	3/4	0.326	10	97160	6
1	1	0.414	10	97165	6



**Viega PEX Press adapter
Zero Lead**
- Bronze
- Press connection, female copper tube size
Model 2813.5ZL

P	C	Wt [lb]	Quantity	Part No	DG
3/8	1/2	0.061	10	92006	6
1/2	1/2	0.063	10	92021	6
1/2	3/4	0.098	10	92026	6
3/4	1/2	0.066	10	92036	6
3/4	3/4	0.116	10	92041	6
3/4	1	0.172	10	92045	6
1	1	0.187	10	92060	6
1 1/4	1 1/4	0.331	5	92070	6
1 1/2	1 1/2	0.450	5	92080	6
2	2	0.609	5	92090	6



Viega PEX Press adapter
- Bronze
- Press connection, street
Model 2813.1NG

P	FTG	Wt [lb]	Quantity	Part No	DG
5/8	1/2	0.077	5	87530	4
5/8	3/4	0.119	5	87531	4



**Viega PEX Press adapter
Zero Lead**
- Bronze
- Press connection, street
Note
ProPress tool and jaw required
Model 2813.1ZL

P	FTG	Wt [lb]	Quantity	Part No	DG
1/2	1/2	0.064	10	97520	6
1/2	3/4	0.097	10	97525	6
3/4	1/2	0.079	10	97535	6
3/4	3/4	0.100	10	97540	6
3/4	1	0.154	10	97545	6
1	1	0.174	10	97560	6
1 1/4	1 1/4	0.304	5	97570	6
1 1/2	1 1/2	0.434	5	97580	6
2	2	0.696	5	97590 ¹	6

¹ For use with solder fittings only.

Couplings



Viega PEX Press coupling
- Bronze
- Press connection
Model 2815NG

P1	P2	Wt [lb]	Quantity	Part No	DG
5/16	5/16	0.032	5	83001	4
5/8	5/8	0.067	5	83030	4



**Viega PEX Press coupling
Zero Lead**
- Bronze
- Press connection
Model 2815ZL

P1	P2	Wt [lb]	Quantity	Part No	DG
3/8	3/8	0.040	10	93000	6
1/2	3/8	0.048	10	93005	6
1/2	1/2	0.050	10	93020	6
3/4	1/2	0.068	10	93050	6
3/4	3/4	0.072	10	93040	6
1	3/4	0.115	10	93055	6
1	1	0.130	10	93060	6
1 1/4	3/4	0.187	5	93071	6
1 1/4	1	0.207	5	93065	6
1 1/4	1 1/4	0.260	5	93070	6
1 1/2	3/4	0.234	5	93072	6
1 1/2	1	0.246	5	93073	6
1 1/2	1 1/4	0.289	5	93075	6
1 1/2	1 1/2	0.318	5	93080	6
2	1 1/2	0.491	5	93091	6
2	2	0.580	5	93090	6