


SIZE	DIMENSIONS			HEX BUSHINGS
INCH	A	B	C	
1/4X1/8	0.44	0.26	0.14	
3/8X1/8	0.48	0.25	0.16	
3/8X1/4	0.48	0.4	0.16	
1/2X1/8	0.56	0.25	0.19	
1/2X1/4	0.56	0.32	0.19	
1/2X3/8	0.56	0.41	0.19	
3/4X1/8	-	-	-	
3/4X1/4	0.63	0.32	0.22	
3/4X3/8	0.63	0.36	0.22	
3/4X1/2	0.63	0.53	0.22	
1X1/4	0.75	0.32	0.3	
1X3/8	0.75	0.36	0.3	
1X1/2	0.75	0.43	0.25	
1X3/4	0.75	0.5	0.25	
1 1/4X1/4	-	-	-	
1 1/4X3/8	-	-	-	
1 1/4X1/2	0.8	0.43	0.34	
1 1/4X3/4	0.8	0.5	0.28	
1 1/4X1	0.8	0.58	0.28	
1 1/2X1/4	-	-	-	
1 1/2X3/8	-	-	-	
1 1/2X1/2	0.83	0.43	0.37	
1 1/2X3/4	0.83	0.5	0.37	
1 1/2X1	0.83	0.58	0.31	
1 1/2X1 1/4	0.83	0.71	0.31	
2X1/2	-	-	-	
2X3/4	-	-	-	
2X1	0.88	0.58	0.41	
2X1 1/4	0.88	0.67	0.34	
2X1 1/2	0.88	0.7	0.34	
2 1/2X1	-	-	-	
2 1/2X1 1/4	-	-	-	
2 1/2X1 1/2	-	-	-	
2 1/2X2	1.07	0.75	0.37	
3X1 1/2	-	-	-	
3X2	1.13	0.75	0.48	
3X2 1/2	1.13	0.92	0.4	
4X1 1/2	-	-	-	
4X2	1.22	0.75	0.6	
4X2 1/2	1.22	0.92	0.6	
4X3	1.22	0.98	0.5	